
## RPG 4700 Inline Mode Wiring Schematic



**LEGEND** 



Copper core low impedence ignition cables



Resistive radio supression ignition cables



Copper wire to +12V of negative grounded battery



Chassis ground

In this setup the plasma spark has to jump across 2 spark gaps in series (one in the distributor, and one at the spark plug tip) thus dissipating some of its energy at the distributor.

For maximum plasma energy delivery to the spark plug Bypass Mode Install is recommended.